

CableHome® - DOCSIS® - PacketCable™ Certified Products - 12/09/05

CH = CableHome D = DOCSIS PC = PacketCable

Beginning with Certification Wave 28, products may be awarded certification/qualification of multiple specifications through the CableLabs "combined certification program".

Note that combined certification will not apply retroactively to any product certified prior to Certification Wave 28, unless that product is submitted for re-certification.

Disclaimer: The model number, software version and hardware version information is provided by the vendor when submitting product for certification and CableLabs assumes no responsibility for accuracy or completeness of that information.

* This product is certified only for the uses as defined in the executive summary of the certification application.

| CW | Version | Type | Manufacturer | CL ID | Model # | SW Version | HW Version | OEM Vendor ID | Spec Combo - Certified As | Verified For Interoperability |
|----|---------------|---------------|---------------------|----------|----------------------------|------------------------------|----------------------|------------------------|---------------------------|-------------------------------|
| 40 | D2.0 | CM | Electroline | Elec401 | DHT-PS-NA-02 | 1.00 | 01 | | D1.1, D2.0 | |
| 40 | D2.0 | CM | Amco Communications | Amco401 | Model 9360 | 1.0 | 5 | | D1.1, D2.0 | |
| 40 | D2.0 | CM | Scientific Atlanta | Scie401 | DPC2100R2 | v2.0.2r1256 | 2,1 | | D1.1, D2.0 | |
| 40 | PC1.0 in D2.0 | EMTA | Asustek | Asus401 | ACM6149 | 3.9.4R1000 | 1.10a | | D1.1, D2.0, PC1.0 | |
| 40 | PC1.5 in D2.0 | EMTA | Terayon | Tera401 | TJ955 | 17.2.0.7 | 58.0 | | D1.1, D2.0, PC1.0, PC1.5 | |
| 40 | PCMM in D1.1 | CMTS | Bigband Networks | 2Bigb401 | Cuda 12000 | R6.0.0 | Rev 4 | | D1.1, PCMM | |
| 40 | PCMM in D1.1 | CMTS | Cisco | 2Cisc401 | uBR7246 VXR/MC28U | 12.3(13a)BCc | MC28U:Rev 6.5 | | D1.1, PCMM | |
| 40 | P1.0 | MG | Siemens | 4Siem401 | hiG 1200 | 11.80.01.33 | S50043-B1606-X-5 | | PC1.0 | |
| 40 | PCMM | Policy Server | Juniper | 5Jnpr401 | SDX-S1-62300 | 6.2.0 | NA | | PCMM | |
| 39 | C1.1 | Embedded PS | SMC | Smcn391 | SMC8014WG-CHM | 3.17.11 | 1.65 | | D1.1, D2.0, CH1.1 | |
| 39 | D2.0 | eCMM | Askey | Aske391 | CMM300 | 2.0.3.8.5 | 1.0 | | D1.1, D2.0 | |
| 39 | D2.0 | CM | WideView Technology | Wide391 | WM-100 | 17.1.7.17 | 35.4.2 | | D1.1, D2.0 | |
| 38 | PC1.0 in D2.0 | EMTA | Thomson | Thom382 | DHG525 | ST62.08.00 | 5.0 | | D1.1, D2.0, PC1.0 | |
| 38 | PC1.0 in D2.0 | EMTA | Cisco-Linksys | Link381 | CMP300B | 17.0.5.23 | 58.0 | | D1.1, D2.0, PC1.0 | |
| 38 | PC1.0 in D2.0 | EMTA | Cisco-Linksys | Link382 | CMP200B | 2.0.3.7.16 | 1.0 | | D1.1, D2.0, PC1.0 | |
| 38 | C1.1 | Embedded PS | Cisco-Linksys | Link383 | WCG104 | 2.0.3.7.16 | 2.0 | | D1.1, D2.0, CH1.1 | |
| 38 | D2.0 | DSG eCM | Pace | Pace381 | TDC775D | 3.7.16001 | V1.0 | | D1.1, D2.0 | X |
| 38 | D2.0 | CM | Arris | Arri381 | TM502G | 4.5.0 | 01 | | D1.1, D2.0 | |
| 38 | D1.1 | CM | Tollgrade | Toll381 | 1.0.0 | 1.0.2 | 1.0.0 | | D1.1 | |
| 38 | D2.0 | CM | Alpha | Alpha381 | Alpha CM-H | 2.01.01AH1.0 | 1.0 | | D1.1, D2.0 | |
| 38 | PC1.0 in D2.0 | EMTA | Motorola | Moto382 | SBV5200 | SBV5200-2.1.3710.1-SCM00-SH | 1 | | D1.1, D2.0, PC1.0 | |
| 38 | PC1.0 in D2.0 | EMTA | Motorola | Moto383 | SBV5121 | SBV5121-2.17.5.23-SCM01-NOSH | 1 | | D1.1, D2.0, PC1.0 | |
| 38 | PC1.0 in D2.0 | EMTA | Pace | Pace | DV315 | v05.38.01 | V1.0 | | D1.1, D2.0, PC1.0 | |
| 38 | PC1.0 in D2.0 | EMTA | Scientific Atlanta | Scie382 | DPC2203 | v2.0.2r1254 | 1.0 | | D1.1, D2.0, PC1.0 | |
| 38 | PC1.0 in D2.0 | EMTA | Scientific Atlanta | Scie381 | DPC2223 | v2.0.2r1154 | 1.0 | | D1.1, D2.0, PC1.0 | |
| 38 | C1.1 | Embedded PS | Motorola | Moto381 | SBG940 | SBG940-2.1.1.1-SCM01-NOSH | 1 | | D1.1, D2.0, CH1.1 | |
| 38 | PC1.0 in D2.0 | EMTA | Thomson | Thom381 | DHG535 | ST70.01.00 | 1.0 | | D1.1, D2.0, PC1.0 | |
| 38 | PC1.0 in D2.0 | EMTA | Ambit | Ambi381 | U10C021 | 4.71.1001 | 2.31 | | D1.1, D2.0, PC1.0 | |
| 37 | P1.1 | MGC | Nortel | 3Nort371 | CS 2000 MGC | SN08.PSM | SN08.PHM | | PC1.0, PC1.1 | |
| 37 | D2.0 | CM | Motorola | Moto371 | SB5121 | SB5121-2.17.0.12-SCM01-NOSH | 1.0 | | D1.1, D2.0 | |
| 37 | D2.0 | CM | Turbocomm | Turb371 | EC420 | 17.0.1.11 | 29.2 | | D1.1, D2.0 | |
| 37 | P1.1 | CMS | Nortel | 0Nort371 | CS 2000 CMS | SN08.PSC | SN08.PHC | | PC1.0, PC1.1 | |
| 37 | P1.1 | MG | Nuera | 4Nuer371 | BTX-4K | 1.1 | A | Sun Microsystems Netra | PC1.0, PC1.1 | |
| 37 | P1.1 | CMS | Siemens | 0Siem371 | Surpass hiQ 8000 | 08.04.01.US.05 | 1400T | Sun Microsystems Netra | PC1.0, PC1.1 | |
| 37 | P1.1 | MGC | Siemens | 3Siem371 | Surpass hiQ 8000 | 08.04.01.US.05 | 1400T | | PC1.0, PC1.1 | |
| 37 | D2.0 | CM | Asustek | Asus371 | ACM6049EB | 3.7.7 | 3.00 | | D1.1, D2.0 | |
| 35 | D2.0 | CM | Arris | Arri351 | TTM402P Phase 2 | 4.4.1 | 32 | | D1.1, D2.0 | |
| 35 | D1.1 | CM | Toshiba | Tosh352 | PCX2000 | 2.1R.007 | 3.2.1 | | D1.1 | |
| 35 | D2.0 | CM | Toshiba | Tosh351 | PCX3200 | 8.43.2 | 25.0.0 | | D1.1, D2.0 | |
| 34 | PC1.0 in D2.0 | EMTA | Cisco-Linksys | Link341 | CM2P2B | 2.0.3.5.10 | 2.1 | | D1.1, D2.0, PC1.0 | |
| 34 | PC1.0 in D2.0 | EMTA | Ambit | Ambi341 | U10C017 | 4.36.1018 | 2.22 | | D1.1, D2.0, PC1.0 | |
| 34 | PCMM | Policy Server | C-Cor | 5Ccor341 | Cuda 12000 (C12-DM2x8-2.0) | 1.0 | NA | | PCMM | |
| 34 | D2.0 | CMTS | Bigband Networks | 2Bigb341 | DM2x8-2.0) | R6.0.0 | Rev 4 | | D1.1, D2.0 | |
| 34 | PC1.0 in D2.0 | EMTA | Netgear | Ntgr341 | CVG824G | 3.5.8R01 | 1.00 | | D1.1, D2.0, PC1.0 | |
| 34 | PC1.0 in D2.0 | EMTA | Terayon | Tera341 | TJ945 | 16.0.0.10 | 31.0 | | D1.1, D2.0, PC1.0 | |
| 34 | PC1.0 in D2.0 | EMTA | Thomson | Thom341 | DHG525 | ST62.06.00 | 5.0 | | D1.1, D2.0, PC1.0 | |
| 34 | PCMM in D2.0 | CMTS+MM | Motorola | 2Moto341 | BSR 64000 | 4.1.0T08P10.12.KRAU | CHS-0009-01 | | D2.0, PCMM | |
| 34 | PC1.0 in D2.0 | EMTA | Cisco-Linksys | Link342 | CG2P2WB | 2.0.3.5.10 | 2.1 | | D1.1, D2.0, PC1.0 | |
| 34 | P1.0 | MG | Nuera | 4Nuer341 | BTX-4K | 1.1.0.4 | A | | PC1.0 | |
| 34 | P1.0 | CMS | Sonus | 0Sonu341 | ASX Access Server | V06.01.00F004 | SUNFIRE V120 | | PC1.0 | |
| 34 | P1.1 | MG | Cisco | 4Cisc341 | MGX8880 | 5.50 | VXSM | | PC1.0, PC1.1 | |
| 34 | PCMM | Policy Server | CableMatrix | 5Cabl341 | ODSP | 0.8.6 | NA | | PCMM | |
| 34 | PCMM | Policy Server | Camiant | 5Cami341 | CAMS-2275 | 2.0.0 | Intel SR 1300 Server | | PCMM | |

| CW | Version | Type | Manufacturer | CL ID | Model # | SW Version | HW Version | OEM Vendor ID | Spec Combo - Certified As | Verified For Interoperability |
|----|---------------|----------------|--------------------|----------|--------------------|-----------------------|---------------|---------------|---------------------------|-------------------------------|
| 34 | PCMM | Policy Server | Tazz Networks | 5Tazz341 | TAZZ PCS | PCMM 1.2 | SUN V60/V20z | | PCMM | |
| 34 | PCMM | Policy Server | Telcordia | 5Telc341 | Policy Manager 1.0 | PS-R1.0-200502091200 | SUNW,Ultra-80 | | PCMM | |
| 33 | D2.0 | CM | Cisco-Linksys | Link331 | BEFCMU10 ver. 5 | 2.0.3.5.6 | 2.0 | | D1.1, D2.0 | |
| 33 | PC1.0 in D2.0 | EMTA | Cisco-Linksys | Link333 | CG2P2WB | 2.0.3.5.6 | 2.1 | | D1.1, D2.0, PC1.0 | |
| 33 | PC1.0 in D2.0 | EMTA | Cisco-Linksys | Link332 | CM2P2B | 2.0.3.5.6 | 2.1 | | D1.1, D2.0, PC1.0 | |
| 33 | PC1.0 in D2.0 | EMTA | Scientific Atlanta | Scie332 | DPX2213 | v2.0.2r1251 | 1.0 | | D1.1, D2.0, PC1.0 | |
| 33 | PC1.0 in D2.0 | EMTA | Scientific Atlanta | Scie331 | DPX2203 | v2.0.2r1151 | 2.1 | | D1.1, D2.0, PC1.0 | |
| 33 | C1.1 | Embedded PS | Ambit | Ambi331 | U10C019 | 5.66.1000 | 4.10 | | D1.1, D2.0, CH1.1 | |
| 33 | PC1.0 in D2.0 | EMTA | Thomson | Thom331 | DHG525 | ST62.05.00 | 5.0 | | D1.1, D2.0, PC1.0 | |
| 32 | C1.1 | Embedded PS | Zyxel | Zyxe321 | Prestige 971 | V3.70.01 | V4.1 | | D1.1, D2.0, CH1.1 | |
| 32 | D2.0 | CM | Terayon | Tera321 | TJ716x | 15.0.0.20 | 56.1 | | D1.1, D2.0 | |
| 32 | D2.0 | CM | Zoom | Zoom321 | 5241 | 5.35.33.5 | 100 | Cone291 | D1.1, D2.0 | |
| 32 | D1.0 | DSG eCM | Scientific Atlanta | Scie321 | 8300 DVLPR | 2.23.7 | 1.0 | | D1.0 | X |
| 32 | D2.0 | CMTS+DSG Agent | Motorola | 2Moto321 | BSR 64000 | 4.1.0T08P10.KRAU | CHS-0009-01 | | D1.1, D2.0 | |
| 32 | C1.1 | Embedded PS | Zyxel | Zyxe322 | Prestige 974 | V3.70.01 | V3.9 | | D1.1, D2.0, CH1.1 | |
| 32 | D2.0 | CMTS+DSG Agent | Arris | 2Arri321 | C4-CMTS-2100-1 | CMTS_V04.02.00.10 | 2.0 | | D1.1, D2.0 | |
| 32 | C1.1 | Embedded PS | Cisco-Linksys | Link321 | CG2P2WB | 2.0.3.4.2 | 2.0 | | D1.1, D2.0, CH1.1 | |
| 32 | D2.0 | CM | Arris | Arri321 | TM402G | 4.4.1 | 07 | | D1.1, D2.0 | |
| 32 | D1.1 | CM | Tollgrade | Toll321 | 1.0.0 | 1.0.2 | 1.0.0 | | D1.1 | |
| 32 | C1.1 | Embedded PS | Netgear | Ntgr321 | CG814WG | 3.4.2 | 1.02 | | D1.1, D2.0, CH1.1 | |
| 32 | D1.1 | CMTS+DSG Agent | Bigband Networks | 1Bigb321 | Cuda 12000 | R5.5.0 | Rev 4 | | D1.1 | |
| 32 | C1.1 | Embedded PS | Thomson | Thom321 | DCW725 | ST5A.06.01 | 4.1 | | D1.1, D2.0, CH1.1 | |
| 31 | D1.1 | CM | AM Communications | Amco311 | 9362 | 1.68 | 4.0 | | D1.1 | |
| 31 | D1.1 | CM | Tollgrade* | Toll311 | 1.0.0 | 1.0.2 | 1.0.0 | | D1.1 | |
| | | | | | | SBV5220-2.10.0.0- | | | | |
| 31 | PC1.0 in D2.0 | EMTA | Motorola | Moto311 | SBV5220 | SCM11-NOSH | 1 | | D1.1, D2.0, PC1.0 | |
| 31 | PC1.1 in D1.1 | CMTS+PC | Cisco | 1Cisc311 | uBR7246 VXR/MC28U | 12.2(15)BC2p1 | MC28U:Rev 6.5 | | D1.1, PC1.0, PC1.1 | |
| 31 | D1.1 | CM | Electroline | Elec311 | DHT-PS-NA-01 | 2.14 | 02 | | D1.1 | |
| 30 | C1.1 | Embedded PS | Thomson | Thom302 | DCW725 | ST5A.02.01 | 4.0 | | D1.1, D2.0, CH1.1 | |
| 30 | PC1.0 in D2.0 | EMTA | Scientific Atlanta | Scie301 | DPX2203 | v2.0.2r1143 | 2.1 | | D1.1, D2.0, PC1.0 | |
| 30 | D1.1 | CM | Electroline | Elec302 | DHT-PS-NA-01 | 2.10 | 01 | | D1.1 | |
| 30 | D2.0 | CM | Terayon | Tera301 | TJ716x | 14.0.1.4101 | 35.0 | | D1.1, D2.0 | |
| | | | | | | SBV5220-2.9.1.0- | | | | |
| 30 | D2.0 | CM | Motorola | Moto301 | SBV5220 | SCM08-NOSH | 1 | | D1.1, D2.0 | |
| 30 | PC1.0 in D2.0 | EMTA | Cisco-Linksys, LLC | Link302 | CG2P2WB | 2.0.3.2.5 | 2.0 | | D1.1, D2.0, PC1.0 | |
| 30 | PC1.0 in D2.0 | EMTA | Ambit | Ambi301 | U10C017 | 4.36.1007 | 2.22 | | D1.1, D2.0, PC1.0 | |
| 30 | D2.0 | CMTS | Motorola | 2Moto301 | BSR 64000 | 4.1.0T04P08.KRAU | CHS-0009-01 | | D1.1, D2.0 | |
| 30 | PC1.0 in D2.0 | EMTA | Cisco-Linksys, LLC | Link301 | CM2P2B | 2.0.3.2.5 | 2.0 | | D1.1, D2.0, PC1.0 | |
| 29 | D2.0 | CM | Thomson | Thom291 | DCM425 | ST52.01.02 | 4.0 | | D1.1, D2.0 | |
| 29 | D2.0 | CM | Ambit | Ambi291 | U10C018 | 2.93.1003 | 1.20 | | D1.1, D2.0 | |
| 29 | D2.0 | CM | Cisco-Linksys | Link291 | BEFCMU10 ver. 4 | 2.0.3.1.1 | 2.0 | | D1.1, D2.0 | |
| 29 | D2.0 | CM | Conexant | Cone291 | ACM951 | 5.35.33.5 | 100 | | D1.1, D2.0 | |
| | | | | | | SB5120-2.13.0.2- | | | | |
| 29 | D2.0 | CM | Motorola | Moto291 | SB5120 | SCM05-NOSH | 4 | | D1.1, D2.0 | |
| 29 | D2.0 | CM | Scientific Atlanta | Scie291 | WebSTAR DPC2100 | v2.0.2r1142 | 1.2 | | D1.1, D2.0 | |
| 29 | D2.0 | CM | Scientific Atlanta | Scie292 | WebSTAR DPC2100 | v2.0.2r1242 | 2.0 | | D1.1, D2.0 | |
| 29 | C1.1 | Embedded PS | Cisco-Linksys | Link292 | WCG200 ver. 2 | 2.0.3.1.1 | 2.0 | | D1.1, D2.0, CH1.1 | |
| 29 | D1.1 | CMTS | ADC | 1Adco291 | Cuda 12000 | R5.5.0 | Rev4 | | D1.0, D1.1 | |
| 29 | D2.0 | CMTS | Arris | 2Arri291 | C4-CMTS-2100-1 | CMTS_V04.00.00.104 | 2.0 | | D1.1, D2.0 | |
| 29 | D1.1 | CMTS | Motorola | 1Moto292 | BSR 64000 | 3.1.0T00P57.05.KRBU | CHS-0009-01 | | D1.1 | |
| 29 | PC1.1 in D1.1 | CMTS+PC | Motorola | 1Moto291 | BSR 64000 | 3.1.0T00P57.05.KRBU | CHS-0009-01 | | D1.1, PC1.0, PC1.1 | |
| 29 | P1.0 | MG | AudioCodes | 4Audc291 | Mediant 5000 | 2.0.30_1.6 | Rev. B | | PC1.0 | |
| 29 | P1.0 | MG | General Bandwidth | 4Gene291 | G6 | rel_1001_0_0_BX | 1.0 | | PC1.0 | |
| | | | | | | SBV5120-2.9.0.1- | | | | |
| 29 | PC1.0 in D2.0 | EMTA | Motorola | Moto292 | SBV5120 | SCM16-NOSH | 1 | | D1.1, D2.0, PC1.0 | |
| 29 | C1.1 | PS | Cisco-Linksys | Link293 | CGV2W | 2.0.3.1.0 | 2.0 | | D1.1, D2.0, CH1.1 | |
| 29 | D2.0 | CM | Conexant | Cone292 | XCM951 | 5.35.33.5 | 10 | | D1.1, D2.0 | |
| 28 | D2.0 | CM | Daehanet | Daeh281 | LP3200 | 10.2.0 | 29.2 | JHCO261 | D1.1, D2.0 | |
| 28 | D2.0 | CM | Castlenet | Cast281 | DP1110XB2A | 2.7.2.280 | 1.0 | | D1.1, D2.0 | |
| 28 | D2.0 | CM | Motorola | Moto286 | SBG900 | 2.1.8.2SCM01 | 3 | | D1.1, D2.0 | |
| | | | | | | SBG940-2.1.8.1-SCM00- | | | | |
| 28 | C1.0 | Embedded PS | Motorola | Moto282 | SBG940 | NOSH | 1 | | D1.1, D2.0, CH1.0 | |
| | | | | | | SBG940-2.1.8.1-SCM00- | | | | |
| 28 | D2.0 | CM | Motorola | Moto281 | SBG940 | NOSH | 1 | | D1.1, D2.0 | |
| | | | | | | SBV5120-2.8.0.4- | | | | |
| 28 | D2.0 | CM | Motorola | Moto283 | SBV5120 | SCM02-NOSH | 1 | | D1.1, D2.0 | |
| 28 | D2.0 | CM | D-Link | Dlin281 | DCM-202 | 2.0.1 | 1A | Hitr252 | D2.0 | |

| CW | Version | Type | Manufacturer | CL ID | Model # | SW Version | HW Version | OEM Vendor ID | Spec Combo - Certified As | Verified For Interoperability |
|----|---------------|-------------|--------------------|-----------|----------------------|---------------------------|----------------|------------------------|---------------------------|-------------------------------|
| 28 | D2.0 | CM | Shenzhen Coship | Cosh281 | CCM2000A | 12.0.2.13 | 35.0 | | D1.1, D2.0 | |
| 28 | D2.0 | CM | Askey | Aske281 | CME100 | 2.0.2.0.6 | 2.1 | | D1.1, D2.0 | |
| 28 | C1.0 | Embedded PS | Ambit | Ambi282 | 60740EU | 5.11.1111 | 4.7 | | D1.1, CH1.0 | |
| 28 | D2.0 | CM | Castlenet | Cast282 | DP1110XB2 | 2.5.2.117 | 1 | | D1.1, D2.0 | |
| 28 | D2.0 | CM | Motorola | Moto287 | SB5101 | SB5101-2.4.0.1-SCM00-NOSH | 1 | | D1.1, D2.0 | |
| 28 | D2.0 | CM | Ambit | Ambi281 | 10018EU | 2.93.1000 | 1.18 | | D1.1, D2.0 | |
| 28 | PC1.1 in D1.1 | CMTS+PC | Cisco | 1Cisc281 | uBR7246 VXR/MC28U | 12.2(15)BC2p | MC28U: Rev 6.5 | | D1.1, PC1.0, PC1.1 | |
| 28 | D2.0 | CM | Thomson | Thom281 | DCM325 | ST32.0D.00 | 1.7 | | D1.1, D2.0 | |
| 28 | C1.1 | Embedded PS | Netgear | Ntgr281 | CG814WG | 2.10.0R01 | 1.02 | | D1.1, D2.0, CH1.1 | |
| 28 | C1.1 | Embedded PS | Cisco-Linksys | Link281 | WCG200 | 2.0.2.10.0 | 1.2b | | D1.1, D2.0, CH1.1 | |
| 28 | D2.0 | CMTS | Arris | 2Arri281 | 710622 (C3) | 4.0.1.45 | 04 | | D1.1, D2.0 | |
| 28 | D2.0 | CM | Conexant | Cone281 | ACM951 | 5.29.30.6.MOOB | 100 | | D1.1, D2.0 | |
| 28 | D2.0 | CM | Conexant | Cone282 | XCM951 | 5.29.30.6.MIAMI | 010 | | D1.1, D2.0 | |
| 28 | P1.0 | CMS | Siemens | 0Siem281 | Surpass hiQ 8000 | 06.02.01.US.09 | 1400T | Sun Microsystems Netra | PC1.0 | |
| 28 | D1.1 | CM | Toshiba | Tosh282 | PCX1100U/DAZ8813 | 1.8.022 | 6.62 | | D1.1 | |
| 28 | D1.0 | CM | Thomson | Thom282 | DCM325 | ST31.08.01 | 1.7 | | D1.0 | |
| 28 | PC1.0 in D2.0 | EMTA | Arris | Arri281 | TM402P | TS.04.01.01.013004C | 04 | | D1.1, D2.0, PC1.0 | |
| 28 | D1.1 | CM | Electroline | Elec281 | DHT-PS-NA-01 | 2.00 | 01 | | D1.1 | |
| 28 | D1.1 | CM | Toshiba | Tosh281 | PCX1100/DAZ8 | 1.8.022 | 6.11 | | D1.1 | |
| 28 | P1.0 | MGC | Nortel Networks | 3Nort281 | CS 2000 MGC | SN06.PSM | SN06.PHM | | PC1.0 | |
| 27 | D2.0 | CM | Cablerex, Inc. | Cabl271 | CRM3800 | 7.0.2 | 6.0.1 | Xros241 | D2.0 | |
| 27 | D2.0 | CM | Motorola | Moto272 | SBG900 | SBG900-2.1.6.0-SCM04-NOSH | 2 | | D2.0 | |
| 27 | D2.0 | CM | Motorola | Moto273 | SB5100 | SB5100-2.3.1.6-SCM01-NOSH | 3 | | D2.0 | |
| 27 | D2.0 | CM | Scientific Atlanta | Scie273 | WebSTAR DPC2100 | v2.0.1r1133 | 1.1 | | D2.0 | |
| 27 | D2.0 | CM | Thomson | Thom271 | DCM315 | ST32.0A.00 | 3.1 | | D2.0 | |
| 27 | D2.0 | CM | Toshiba | Tosh271 | PCX2600/DAZ8823 | 3.0.14 | 19.0.1 | | D2.0 | |
| 27 | C1.0 | Embedded PS | Netgear | Ntgr271 | CG814WG | 2.92R01 | 1.02 | | CH1.0 | |
| 27 | C1.0 | Embedded PS | Scientific Atlanta | Scie272 | WebSTAR DPR2320 | v2.0.1r1133 | 1.1 | | CH1.0 | |
| 27 | D1.1 | CMTS | Cisco | 1Cisco271 | uBR7246VXR/MC28U | 12.2(15)CXc1 | MC28U: Rev 6.2 | | D1.1 | |
| 27 | D2.0 | CM | Scientific Atlanta | Scie274 | WebSTAR DPX2100 | v2.0.1r1134 | 1.3 | | D2.0 | |
| 27 | D2.0 | CM | Zyxel | Zyxe271 | Prestige 964 | SW_REV:3.61 | HW_REV:3.6 | | D2.0 | |
| 27 | C1.0 | Embedded PS | Ambit | Ambi272 | 60740EUW | 5.11.1111 | 4.7 | | CH1.0 | |
| 27 | D2.0 | CM | Cisco-Linksys | Link271 | BEFCMU10 ver.3 | 2.0.2.0.1 | 1.0 | | D2.0 | |
| 27 | P1.0 | CMS | Cedar Point | 0Ceda271 | SAFARI | R3.0.9.3 | 1.2 | | PC1.0 | |
| 27 | P1.0 | CMS | Cisco | 0Cisc271 | BTS10200 | RSL4.1Q11 | BTS10200 | | PC1.0 | |
| 27 | PC1.0 in D2.0 | EMTA | Scientific Atlanta | Scie271 | WebSTAR DPX2203 | v2.0.1r1133 | 1.1 | | PC1.0 | |
| 27 | D2.0 | CM | Terayon | Tera272 | TJ815g | 4.21.5 | 41.0 | | D2.0 | |
| 27 | C1.0 | Embedded PS | Motorola | Moto271 | SGB900 | SBG900-2.1.6.2-SCM02-NOSH | 2 | | CH1.0 | |
| 27 | D1.1 | CM | Best Data | Best271 | CMX300v2 | 0.14457.2570 | 10 | Cast261 | D1.1 | |
| 27 | P1.0 | MGC | Cisco | 3Cisc271 | BTS10200 | RSL 4.1Q11 | BTS10200 | | PC1.0 | |
| 27 | P1.0 | CMS | Telcordia | 0Telc271 | Telcordia Call Agent | 2.3.3 | Sun Ultra 80 | | PC1.0 | |
| 26 | D1.1 | CM | Cisco | Cisc261 | Ubr925 | 12.2 | 3i | | D1.1 | |
| 26 | D1.1 | CM | Castlenet | Cast262 | CXC250 | 5.19.20.2.FORTMESH.2 | 010 | | D1.1 | |
| 26 | C1.0 | Embedded PS | Scientific Atlanta | Scie263 | WebSTAR DPR2320 | v2.0.1r1132 | 1.1 | | CH1.0 | |
| 26 | C1.0 | Embedded PS | Netgear | Ntgr261 | CG814WG | 2.90R01 | 1.02 | | CH1.0 | |
| 26 | D1.1 | CM | Linksys | Link264 | WCG200 | 1.1.3.0.1 | 1.2b | | D1.1 | |
| 26 | D2.0 | CM | Motorola | Moto262 | SBG900 | SBG900-2.1.3.4-SCM09-NOSH | 1 | | D2.0 | |
| 26 | D2.0 | CM | Motorola | Moto261 | SB5100 | SB5100-2.3.0.9-SCM01-NOSH | 3 | | D2.0 | |
| 26 | D2.0 | CM | Scientific Atlanta | Scie265 | WebSTAR DPC2100 | v2.0.1r1132 | 1.0 | | D2.0 | |
| 26 | D2.0 | CM | Askey | Aske261 | CME100 | 2.0.2.0.1 | 2.1 | | D2.0 | |
| 26 | D2.0 | CM | JooHong | Jhco261 | SL2810 | 10.2.0 | 29.2 | | D2.0 | |
| 26 | D2.0 | CM | Zyxel | Zyxe261 | Prestige 964 | 3.60 | 3.6 | | D2.0 | |
| 26 | D1.0 | CM | Thomson | Thom262 | DCM625/DCM625R | ST41.03.00 | 1.1 | | D1.0 | |
| 26 | D1.1 | CM | Linksys | Link261 | BEFCMU10 ver.3 | 1.1.1.0.1 | 1.0 | | D1.1 | |
| 26 | D1.1 | CM | Thomson | Thom265 | DCW615 (DCW615R) | ST49.04.00 | 1.4 | | D1.1 | |
| 26 | D2.0 | CM | Terayon | Tera262 | TA-102 | 6.0.1v | 9.3 | | D2.0 | |
| 26 | PC1.0 in D2.0 | EMTA | Scientific Atlanta | Scie264 | WebSTAR DPX2203 | v2.01r1132 | 1.1 | | PC1.0 | |
| 26 | P1.0 | MG | Nuera | 4Nuer261 | BTX-8 | 2.0 | 2.0 | | PC1.0 | |
| 26 | P1.0 | CMS | Nortel Networks | 0Nort261 | CS2000 | SN06.PSC | SN06.PHC | | PC1.0 | |
| 26 | P1.0 | CMS | Cedar Point | 0Ceda261 | SAFARI | 2.0.7.3 | 1.1 | | PC1.0 | |

| CW | Version | Type | Manufacturer | CL ID | Model # | SW Version | HW Version | OEM Vendor ID | Spec Combo - Certified As | Verified For Interoperability |
|----|---------------|-------------|--------------------|-----------|--------------------------------|----------------------------|---------------------|---|---------------------------|-------------------------------|
| 26 | D1.1 | CM | Ambit | Ambi261 | 60678EU | 2.57.1002 | 1.12 | | D1.1 | |
| 26 | D1.0 | CM | Scientific Atlanta | Scie261 | WebSTAR DPX2100 | v1.0.1r1131-0424 | 1.11 | | D1.0 | |
| 26 | D2.0 | CM | Terayon | Tera263 | TJ715X | 6.22 | 10.0 | | D2.0 | |
| 26 | D2.0 | CM | Texas Instruments | Texa261 | TNETC421A | 10.2.4 | 51.2 | | D2.0 | |
| 26 | PC1.0 in D1.1 | CMTS+PC | ADC | 1Adco261 | Cuda 12000 (C-12 DM1X6SPME-SF) | R5.0.0 | CMTS: Rev 14 | | PC1.0 | |
| 26 | D1.1 | CMTS | Arris | 1Arri261 | CMTS 2000 | 3.2.1.100.001 | 2 | | D1.1 | |
| 26 | D1.0 | CM | Thomson | Thom261 | DCM315/DCM315R | ST31.07.00 | 1.3 | | D1.0 | |
| 26 | D1.1 | CM | Belkin | Belk261 | F5D5530-W | 0.14457.2571 | 10 | | D1.1 | |
| 26 | D1.1 | CM | Linksys | Link263 | WCG200 | 1.1.3.0.1 | 1.2b | | D1.1 | |
| 26 | D1.1 | CM | SMC | Smcn262 | SMC8004CM | 2.0.1 | 1A | Hitr251 | D1.1 | |
| 26 | D1.1 | CM | Castlenet | Cast261 | CXC-150 | 0.14457.2570 | 10 | | D1.1 | |
| 26 | D1.1 | CM | Motorola | Moto263 | SBG1000 | SBG1000-1.1.3.5-SCM00-NOSH | 1 | | D1.1 | |
| 26 | D1.1 | CM | Toshiba | Tosh263 | PCX2200/DAZ8817 | 1.8.017 | 7.4 | | D1.1 | |
| 26 | D1.0 | CM | Thomson | Thom264 | DCM315/DCM315R | ST31.08.00 | 1.5 | | D1.0 | |
| 26 | D2.0 | CM | Thomson | Thom263 | DCM316/DCM316R | ST36.10 | 50.1 | | D2.0 | |
| 26 | D1.1 | CM | Motorola | Moto264 | SB3100 | SB3100-1.4.8.13-SCM01-NOSH | 1 | | D1.1 | |
| 25 | C1.0 | Embedded PS | Thomson | Thom254 | DCW615/DCW615R | 2.82R03 | 1.40 | | CH1.0 | |
| 25 | C1.0 | Embedded PS | Linksys | Link256 | WCG200 | 2.0.1.0.2 | 1.0b | | CH1.0 | |
| 25 | D1.1 | CM | Linksys | Link251 | BEFCMU10 | 1.1.5 | 3.0 | | D1.1 | |
| 25 | P1.0 | CMS | Cisco | 0Cisc251 | BTS10200 | R4.0 | R4.0 | | PC1.0 | |
| 25 | PC1.0 in D1.1 | CMTS+PC | Cisco | 1Cisc253 | uBR7246vrxr | 12.2(11)BC2p | 1.03 | rev B0, MC16S rev 1.0, NPE400: Rev A0, HW | PC1.0 | |
| 25 | PC1.0 in D1.1 | CMTS+PC | Motorola | 1Motor251 | BSR64000 | 1.3.0T04P21.KRAU | PCA-0100 | | PC1.0 | |
| 25 | PC1.0 in D2.0 | CMTS+PC | Terayon | 2Tera251 | BW3500 | 2.0.0.1.21 | 2.0 | | PC1.0 | |
| 25 | PC1.0 in D1.1 | CMTS+PC | Cisco | 1Cisc251 | uBR10012 | 12.2(11)BC2p | Rev 4.0 MC28 Rev A0 | | PC1.0 | |
| 25 | D2.0 | CM | Motorola | Moto253 | SB5120 | NOSH | 1 | | D2.0 | |
| 25 | D1.1 | CM | Linksys | Link257 | WCG200 | 2.0.1.0.1 | 10.b | | D1.1 | |
| 25 | D1.1 | CM | Scientific Atlanta | Scie252 | WebSTAR DPX100 | 1.1.2r1.1.3.1 | 2.1 | | D1.1 | |
| 25 | D1.1 | CM | SMC | Smcn253 | SMC8013WG | 2.0.0 | 1A | | D1.1 | |
| 25 | D1.1 | CM | Terayon | Tera251 | TA-102 | 2215 | 8.15 | | D1.1 | |
| 25 | D1.1 | CM | Terayon | Tera252 | TJ715 | 5.26 | 9.0 | | D1.1 | |
| 25 | D1.1 | CM | Thomson | Thom253 | DCW615,DCW615R | 2.81R01 | 1.40 | | D1.1 | |
| 25 | D2.0 | CM | Ambit | Ambi251 | 60678EU | 2.57.2007 | 1.12 | | D2.0 | |
| 25 | D2.0 | CM | Arris | Arri253 | CM450A | CM.04.02.011703C | 01 | | D2.0 | |
| 25 | D2.0 | CM | Castlenet | Cast253 | CXC250 | 5.12121 | 010 | | D2.0 | |
| 25 | D2.0 | CM | Com21 | Cmto251 | DP1110XB2 | 2.5.2.111 | 1 | | D2.0 | |
| 25 | D1.1 | CM | Kinpo | Kipo251 | CMD1001 | 5.26 | 7.0 | | D1.1 | |
| 25 | D2.0 | CM | Linksys | Link255 | WCG200 | 2.0.1.0.1 | 1.0b | | D2.0 | |
| 25 | D1.1 | CM | Arris | Arri252 | CM450A | CM.04.02.011703C | 01 | | D1.1 | |
| 25 | D2.0 | CM | Motorola | Moto256 | SB5120 | SB5120-2.9.2.9-SCM-03-NOSH | 2 | | D2.0 | |
| 25 | D2.0 | CM | Scientific Atlanta | Scie251 | WebSTAR DPX2100 | 2.0.1r1.1.3.1 | 1.1 | | D2.0 | |
| 25 | D2.0 | CM | Terayon | Tera253 | TJ715 | 6.20 | 9.0 | | D2.0 | |
| 25 | D2.0 | CM | Terayon | Tera254 | TJ715 | 6.20 | 7.0 | | D2.0 | |
| 25 | D2.0 | CM | Thomson | Thom252 | DCM315,DCM315R | ST32.06.00 | 1.2 | | D2.0 | |
| 25 | D2.0 | CM | Toshiba | Tosh252 | PCX2600/DAZ8823 | 3.0.13 | 19.0.0 | | D2.0 | |
| 25 | D1.1 | CM | Netgear | Ntgr251 | CG814Mv2 | 2.0.0 | 1A | | D1.1 | |
| 25 | D1.1 | CM | Motorola | Moto252 | SB5120 | SB5120-2.9.2.9-SCM-03-NOSH | 1 | | D1.1 | |
| 25 | D1.1 | CM | Hitron | Hitr251 | BRG-3520T | 2.0.1 | 1A | | D1.1 | |
| 25 | D1.1 | CM | Correlant | Corr251 | EC330A | 9.2.9 | 17.0 | | D1.1 | |
| 25 | D1.1 | CM | Terayon | Tera255 | TJ715X | 5.25 | 7.0 | | D1.1 | |
| 25 | D2.0 | CM | Hitron | Hitr252 | BRG-3520T | 2.0.1 | 1A | | D2.0 | |
| 25 | D1.1 | CM | D-Link | Dlin251 | DCM-201 | 1.1.0 | 4A | Hitr231 | D1.1 | |
| 25 | PC1.0 in D1.1 | CMTS+PC | Arris | 1Arri251 | C4-CMTS-2100-1 | CMTS_V03.01.00.20 | 1.3 | | PC1.0 | |
| 25 | PC1.0 in D1.1 | EMTA | Motorola | Moto255 | SBV4200 | SBV4200-07.2.04-SCM00-NOSH | 1 | | PC1.0 | |
| 25 | D1.0 | CM | Thomson | Thom251 | DCM315/DCM315R | ST31.04.00 | 1.2 | | D1.0 | |
| 25 | D1.1 | CMTS | Cisco | 1Cisc252 | uBR7114 | 12.2(11)BC3c | Rev 1.3 | | D1.1 | |
| 25 | D1.0 | CM | Toshiba | Tosh251 | PCX2600/DAZ8823 | 1.0.13 | 19.0.0 | | D1.0 | |
| 25 | D1.0 | CM | Toshiba | Tosh253 | PCX4500/DAZ8841 | 1.0.0 | 17.0.0 | | D1.0 | |
| 25 | D1.1 | CM | Motorola | Moto259 | SB3100 | SB3100-1.4.8.13-SCM00-NOSH | 1 | | D1.1 | |

| CW | Version | Type | Manufacturer | CL ID | Model # | SW Version | HW Version | OEM Vendor ID | Spec Combo - Certified As | Verified For Interoperability |
|----|---------------|-------------|--------------------------|----------|------------------|---|----------------|---------------|---------------------------|-------------------------------|
| 25 | PC1.0 in D1.1 | EMTA | Arris | Arri251 | TTM202P | TM.03.02.020703C | 05 | | PC1.0 | |
| 25 | P1.0 | CMS | Syndeo | 0Synd251 | Syion 426 | 2.2.6.8 | Sun Blade 1000 | | PC1.0 | |
| 25 | C1.0 | Embedded PS | Ambit | Ambi253 | 60740EUW | 5.11.1001 | 4.6 | | CH1.0 | |
| 25 | D1.0 | CM | DX Antenna | Dxan251 | CDM-130/DAZ8821 | 1.0.6 | 9.1.1 | Tosh221 | D1.0 | |
| 24 | D1.0 | CM | Thomson | Thom241 | DCM315/DCM315R | ST31.01.00 | 1.1 | | D1.0 | |
| 24 | D1.1 | CM | Arris | Arri243 | TC00DA1430 | 1.1.0 | 02 | | D1.1 | |
| 24 | D1.1 | CM | Pioneer | Pion241 | BT-M850W | 1.1.1 r1 | 1.0 | | D1.1 | |
| | | | | | | SB5100-1.1.1.1-SCM01- | | | | |
| 24 | D1.1 | CM | Motorola | Moto242 | SB5100 | NOSH | 1 | | D1.1 | |
| 24 | D1.1 | CM | Com21 | Com21 | DP1110XB2 | 2.5.2.110 | 1 | | D1.1 | |
| 24 | D1.1 | CM | Askey | Aske241 | CME100 | 1.1.1 r1 | 1.0 | | D1.1 | |
| 24 | D1.1 | CM | Arris | Arri242 | TC00DA103 | 4.2.0 | 01 | | D1.1 | |
| 24 | D1.1 | CM | Arris | Arri241 | TM02DB102 | 3.5.1 | 04 | | D1.1 | |
| 24 | D1.1 | CM | Ambit | Ambi242 | 60678EU | 2.57.1001 | 1.12 | | D1.1 | |
| 24 | D1.1 | CM | Ambit | Ambi241 | 60194E | 2.23.1099 | 1.6 | | D1.1 | |
| 24 | D1.1 | CM | Scientific Atlanta | Scie242 | WebSTAR DPX203 | 1.0.4 r4 | 5.0 | | D1.1 | |
| 24 | D1.0 | CM | Thomson | Thom242 | DCM305/DCM305R | ST23.1B.41 | 028 | | D1.0 | |
| 24 | D2.0 | CM | Terayon | Tera243 | TJ715 | 6.19 | 3.0 | | D2.0 | |
| 24 | D1.1 | CMTS | Scientific Atlanta | 1Scie231 | Prisma G1 | 2.1.1.16B | M2.0-G1 | 1Jnpr231 | D1.1 | |
| 24 | D1.0 | CM | Toshiba | Tosh243 | PCX2200A/DAZ8818 | 1.7.022 | 7.6 | | D1.0 | |
| | | | | | | SB5100-1.1.1.1-SCM01- | | | | |
| 24 | D2.0 | CM | Motorola | Moto243 | SB5100 | NOSH | 1 | | D2.0 | |
| | | | | | | Rev 3.0 MC5x20S rev. | | | | |
| 24 | D1.1 | CMTS | Cisco | 1Cisc241 | UBR10012 | 12.2(11)BC2c1 | 5.0 | | D1.1 | |
| 24 | D2.0 | CMTS | Terayon | 2Tera241 | BW3500 | 2.0.0.021 | 2.0 | | D2.0 | |
| 24 | D1.1 | CMTS | Arris | 1Arri242 | ARCD00048 | 4.2.8 | 01 | | D1.1 | |
| | | | | | | rev B0, MC16S rev 1.0, NPE400: RevA0, HW | | | | |
| 24 | D1.1 | CMTS | Cisco | 1Cisc242 | uBR7200 VXR | 12.2(11)BC1c | 1.03 | | D1.1 | |
| 24 | D2.0 | CM | Texas Instruments | Texa242 | TNETC406 | 27.8.2 | 13.1 | | D2.0 | |
| 24 | D1.1 | CM | Toshiba | Tosh241 | PCX3000/DAZ8831 | 6.2.3 | 13.0.0 | | D1.1 | |
| 24 | D2.0 | CM | Scientific Atlanta | Scie241 | WebSTAR DPX2100 | 2.0.1 r4 | 1.1 | | D2.0 | |
| 24 | D1.1 | CM | Scientific Atlanta | Scie243 | WebSTAR DPR362 | 1.1.1 r3 | 1.0 | | D1.1 | |
| 24 | D2.0 | CM | Xrosstech | Xros241 | XCM-3800 | 7.0.2 | 6.0.1 | | D2.0 | |
| 24 | D1.1 | CM | Toshiba | Tosh245 | PCX201/DAZ7781 | 1.0.0 | 17.0.0 | | D1.1 | |
| 24 | D1.1 | CM | Thomson | Thom244 | DCM318/DCM318R | 5.25 | 8.0 | | D1.1 | |
| 24 | D1.1 | CM | Texas Instruments | Texa241 | CX300 | 8.2.2 | 200.2 | | D1.1 | |
| 24 | D1.1 | CM | Terayon | Tera242 | TJ715 | 5.25 | 7.0 | | D1.1 | |
| 24 | D1.1 | CM | Terayon | Tera241 | TA-102 | 221 | 8.15 | | D1.0, D1.1 | |
| 24 | D1.1 | CM | Kinpo | Kipo241 | CMD1001 | 5.25 | 7.0 | | D1.1 | |
| 24 | C1.0 | Embedded PS | Netgear | Ntgr241 | CG314WH | 2.64 | 1.30 | | CH1.0 | |
| 24 | PC1.0 in D1.1 | EMTA | Arris | Arri241 | TM02DB102 | 3.5.1 | 04 | | PC1.0 | |
| 24 | PC1.0 in D1.1 | EMTA | Toshiba | Tosh262 | PCX3000/DAZ8831 | 7.2.3 | 13.0.0 | | PC1.0 | |
| | | | | | | Rev B0 MC16S rev 1.0, | | | | |
| 24 | PC1.0 in D1.1 | CMTS+PC | Cisco | 1Cisc241 | UBR7246 VXR | 12.2 (11)BC1c | NPE400 | | PC1.0 | |
| 24 | PC1.0 in D2.0 | CMTS+PC | Terayon | 2Tera241 | BW3500 | 2.0.0.0.18 | 2.0 | | PC1.0 | |
| 24 | C1.0 | Embedded PS | Linksys | Link241 | BEFCMUH4 | 2.64 | 1.30 | | CH1.0 | |
| 24 | D1.1 | CM | Broadxent | Broa241 | 8601 | 1.1.5 r1 | 5.2 | | D1.1 | |
| 23 | D1.1 | CMTS | Motorola | 1Moto231 | BSR 64000 | 1.3.0T03P08A.KRBU | PCA-0100 | | D1.1 | |
| 23 | D1.1 | CM | Arris | Arri231 | CM00DA103 | 3.3.0 | 01 | | D1.1 | |
| 23 | D1.1 | CM | Belkin | Belk231 | F5D5530-W | 0.13645.2310 | 10 | | D1.1 | |
| 23 | D1.1 | CM | CastleNet | Cast231 | CXC150 | 0.13645.2310 | 10 | | D1.1 | |
| 23 | D1.1 | CM | Com21 | Com21 | DP1110XB | 2.3.2.109 | 3 | | D1.1 | |
| 23 | D1.1 | CM | Hitron | Hitr231 | BRG-3520 | 1.1.0 | 4A | | D1.1 | |
| 23 | D1.1 | CM | Linksys | Link231 | BEFCMUH4 | 2.63 | 1.30 | | D1.1 | |
| 23 | D1.0 | CM | Toshiba | Tosh232 | PCX5000/DAZ8850 | 1.7.021SV | 7.31 | | D1.0 | |
| 23 | D1.1 | CM | Thomson | Thom231 | DCM305/DCM305R | ST24.13.40 | 028 | | D1.1 | |
| 23 | D1.0 | CM | Toshiba | Tosh233 | PCX2200/DAZ8817 | 1.7.021 | 7.4 | | D1.0 | |
| 23 | D1.1 | CMTS | Terayon | 1Tera231 | BW3500 | 1.3.21.2 | 2.0 | | D1.1 | |
| 23 | D1.1 | CM | Intel | Inte231 | 5200 | 14.5.4 | 9 | | D1.1 | |
| 23 | D1.1 | CMTS | Juniper | 1Jnpr231 | Juniper G1 | 2.1.1.16b | M2.0-01 | | D1.1 | |
| 23 | D1.1 | CM | Linksys | Link233 | BEFCMU10 Ver 2 | 1.1.4 | 4.0 | | D1.1 | |
| 23 | D1.0 | CM | Motorola | Moto232 | SB4300 | 2.7.1b | 1 | | D1.0 | |
| 23 | D1.1 | CM | Askey | Aske231 | CME075 | 1.1.4 r1 | 5.4 | | D1.1 | |
| 23 | D1.0 | CM | Toshiba | Tosh231 | PCX2500/DAZ8821 | 1.0.11 | 9.2.3 | | D1.0 | |
| 23 | D1.0 | CM | Efficient Networks, Inc. | Effi231 | SpeedStream 6101 | 2.22.2 | 1.8 | | D1.0 | |
| | | | | | | SBG1000-0.1.1.1- SCM03-NOSH | | | | |
| 23 | D1.0 | CM | Motorola | Moto231 | SBG1000 | | 1 | | D1.0 | |

| CW | Version | Type | Manufacturer | CL ID | Model # | SW Version | HW Version | OEM Vendor ID | Spec Combo - Certified As | Verified For Interoperability |
|----|---------|------|------------------------|----------|-------------------------------|--------------|---|---------------|---------------------------|-------------------------------|
| 23 | D1.0 | CM | Netgear | Ntgr232 | CG814W | 2.63 | 1.10 | | D1.0 | |
| 23 | D1.0 | CM | Scientific Atlanta | Scie231 | Webstar DPX100 | 1.0.5 r1.1.3 | 2.1 | | D1.0 | |
| 23 | D1.0 | CM | Scientific Atlanta | Scie232 | Webstar DPX2100 | 2.0.1r | 1.0 | | D1.0 | |
| 23 | D1.0 | CM | SMC | Smcn231 | SMC8012WG | 2.63 | 1.00 | | D1.0 | |
| 23 | D1.0 | CM | Thomson | Thom232 | DCW232 | 2.63 | 1.30 | | D1.0 | |
| 23 | D1.0 | CM | Netgear | Ntgr231 | CM212 | 1.01 | 3A | Hitr201 | D1.0 | |
| 22 | D1.1 | CMTS | Arris | 1Arri221 | C4-CMTS-2100-1 | v02.00.02.10 | 1.0 | | D1.1 | |
| 22 | D1.1 | CM | Motorola | Moto224 | SB4200 | 1.4.8.5 | 1 | | D1.1 | |
| 22 | D1.1 | CMTS | Juniper | 1Jnpr221 | Juniper G10 | 2.1.0.18 | 2.0 | | D1.1 | |
| 22 | D1.1 | CM | Motorola | Moto223 | SB4100 | 1.4.8.5 | 0 | | D1.1 | |
| 22 | D1.1 | CM | Texas Instruments | Texa221 | TNETC405T | 6.3.0 | 9.1 | | D1.1 | |
| 22 | D1.1 | CM | Toshiba | Tosh222 | PCX2500/DAZ8821 | 2.0.7 | 9.2.2 | | D1.1 | |
| 22 | D1.1 | CMTS | ADC | 1Adco221 | Cuda 12000 (C12-DM1x6SPM-SF) | R3.1.23 | CMTS: Rev A5 NPE-400: Rev A0 HW 1.03, MC28C: Rev B0 | | D1.1 | |
| 22 | D1.1 | CMTS | Cisco | 1Cisc221 | UBR7200VXR/MC28C | 12.2(7)BC1c | HW 2.03 | | D1.1 | |
| 22 | D1.1 | CMTS | Motorola | 1Moto221 | BSR 64000 | 1.2.47.KRC | PCA-0057-02 | | D1.1 | |
| 22 | D1.1 | CMTS | Motorola | 1Moto222 | BSR 1000 | 01.01.15.PRR | PCA-0027-030 | | D1.1 | |
| 22 | D1.1 | CMTS | Scientific Atlanta | 1Scie221 | Prisma G10 | 2.1.0.18 | 2.0 | 1Jnpr221 | D1.1 | |
| 22 | D1.1 | CMTS | ADC | 1Adco222 | Cuda 12000 (C-12-DM1x4SPM-SF) | R3.1.23 | CMTS: Rev. 23 | | D1.1 | |
| 22 | D1.1 | CM | Fujitsu | Fnts221 | FSC102 | 1.1.2 r1 | 5.1 | ASKE211 | D1.1 | |
| 22 | D1.1 | CM | Motorola | Moto222 | SB4220 | NOSH | 1 | | D1.1 | |
| 22 | D1.0 | CM | Toshiba | Tosh224 | PCX2200 | 1.7.017 | 7.3 | | D1.0 | |
| 22 | D1.1 | CM | Com21 | Com21 | DP 1110XB | 2.3.2.108 | 03 | | D1.1 | |
| 22 | D1.0 | CM | Com21 | Com21 | DP 1110XB | 2.3.1.108 | 3 | | D1.0 | |
| 22 | D1.1 | CM | Correlant | Corr221 | EC270 | 1.8.10 | 7.41 | | D1.1 | |
| 22 | D1.1 | CM | Johohong | Jhco222 | SL-2800 | Ver6.1.0 | Ver2.1 | | D1.1 | |
| 22 | D1.0 | CM | AsusTek | Asus222 | ACM6045EB | 1.9 | 1.4 | | D1.0 | |
| 22 | D1.0 | CM | Linksys | Link222 | BEFCMUH41 | 1.0.0 | 0A | | D1.0 | |
| 22 | D1.0 | CM | Linksys | Link223 | BEFCMUH4 | 2.62 | 1.10 | | D1.0 | |
| 22 | D1.0 | CM | Motorola | Moto221 | SB4220 | NOSH | 1 | | D1.0 | |
| 22 | D1.0 | CM | Pioneer | Pion221 | BT-M800W | 1.0.7 r1 | 3.0 | | D1.0 | |
| 22 | D1.0 | CM | Scientific Atlanta | Scie221 | WebStar DPX100 | 1.0.5 r1.1 | 1.0 | | D1.0 | |
| 22 | D1.1 | CM | 3Com | 3Com221 | 3CR29223 | 02.06 | 2.00 | | D1.1 | |
| 22 | D1.0 | CM | Scientific Atlanta | Scie223 | WebStar DPX100 | 1.0.5 r1.1 | 2.2 | | D1.0 | |
| 22 | D1.0 | CM | Thomson | Thom221 | DCM305/305R | ST22.05.01 | 028 | | D1.0 | |
| 22 | D1.0 | CM | Thomson | Thom222 | DCM305/305R | ST23.10.00 | 028 | | D1.0 | |
| 22 | D1.0 | CM | Toshiba | Tosh221 | PCX2500/DAZ8821 | 1.0.6 | 9.1.1 | | D1.0 | |
| 22 | D1.0 | CM | Scientific Atlanta | Scie222 | WebStar DPX100 | 1.0.5 r1.1 | 2.1 | | D1.0 | |
| 22 | D1.1 | CM | Broadxent | Broa221 | 8601 | 1.1.2 r1 | 5.1 | Aske211 | D1.1 | |
| 22 | D1.1 | CMTS | Arris | 1Arri222 | ARCD00048 | 4.2.6 | 01 | | D1.1 | |
| 21 | D1.1 | CM | Conexant | Cone211 | CX9421CM | 4.12734 | 24943.15.0 | | D1.1 | |
| 21 | D1.1 | CM | Askey | Aske211 | CME075 | 1.1.2 r1 | 5.1 | | D1.1 | |
| 21 | D1.1 | CM | Arris | Arri211 | A2TM02NA | 2.1.0 | 04 | | D1.1 | |
| 21 | D1.1 | CM | SMC | Actn211 | CSMC8011CM-B | 2.3.1 | 3.0 | | D1.1 | |
| 21 | D1.0 | CM | Thomson | Thom212 | RCA DCM305 | ST.22.04.00 | 028 | | D1.0 | |
| 21 | D1.0 | CM | Motorola | Moto214 | SB4200 | 0.4.4.0p | Rev. 1 | | D1.0 | |
| 21 | D1.0 | CM | Motorola | Moto213 | SB4100 | 0.4.4.0p | Rev. 0 | | D1.0 | |
| 21 | D1.0 | CM | Linksys | Link211 | BEFMCU10 ver.2 | 1.0.6 | 4.0 | | D1.0 | |
| 21 | D1.0 | CM | AsusTek | Asus211 | ACM6045EB | 1.80 | 1.00 | | D1.0 | |
| 21 | D1.0 | CM | Aastra | Aast211 | HM300c | 71-0001-10 | ROA 219 767/1 R1A | | D1.0 | |
| 21 | D1.1 | CM | Quanta Network Systems | Quan211 | QCM200 | 2.4.1 | 3.2 | | D1.1 | |
| 21 | D1.0 | CM | DX Antenna | Dxan211 | CDM-120/DAZ8820 | 1.1R.005 | 3.2.1 | Tosh182 | D1.0 | |
| 21 | D1.1 | CMTS | Arris | 1Arri212 | C4-CMTS2100 | V01.01.00.12 | 1.0 | | D1.1 | |
| 21 | D1.0 | CM | Linksys | Link212 | BEFCMU10 | 1.0.4 Rel 2 | 3.0 | | D1.0 | |
| 21 | D1.1 | CM | Samsung | Same211 | SCM-140U | 2.1.0 | 14.00 | | D1.1 | |
| 21 | D1.1 | CM | Scientific Atlanta | Scie212 | WebSTAR DPX213 | 1.1.2 r1 | 1.0 | | D1.1 | |
| 21 | D1.1 | CM | Terayon | Tera211 | ECM615 | 4.34 | 1.3 | | D1.1 | |
| 21 | D1.1 | CM | Terayon | Tera212 | ECM715 | 5.08 | 3.0 | | D1.1 | |
| 21 | D1.1 | CM | Thomson | Thom211 | DCM245/DCM245R | ST.1C.0D.00 | 026 | | D1.1 | |
| 21 | D1.0 | CM | Coresma | Crsm211 | CM6011 | 0.5096.360 | 04 | Cast191 | D1.0 | |
| 21 | D1.0 | CM | Best Data | Best211 | CMX300 | 0.5096.360 | 04 | Cast191 | D1.0 | |

| CW | Version | Type | Manufacturer | CL ID | Model # | SW Version | HW Version | OEM Vendor ID | Spec Combo - Certified As | Verified For Interoperability |
|----|---------|------|--------------------|----------|-----------------------|---------------------|------------------------|------------------|---------------------------|-------------------------------|
| 21 | D1.1 | CM | Xrosstech | Xros211 | XCM-2300 | 5.0.2 | 5.1.2 | | D1.1 | |
| 21 | D1.1 | CMTS | RiverStone | 1Rstn211 | RS 8600 | 8.2.1.1 | Backplane Rev:A | | D1.1 | |
| 21 | D1.0 | CMTS | Terayon | 0Tera212 | B2800 | 6.1.2.C.1 | 300-005-03-0B | RiverStone | D1.0 | |
| 21 | D1.1 | CMTS | ADC | 1Adco211 | Cuda 12000 | R3.1.91 | 1 | | D1.1 | |
| 21 | D1.1 | CMTS | Cisco | 1Cisc211 | UBR10012 | 12.2(4) BCc | Rev 4.0 MC28 RevA0 | | D1.1 | |
| 21 | D1.1 | CM | Tellabs | Tell211 | CVM315A | 2.5.0 | RevA | | D1.1 | |
| 21 | D1.0 | CMTS | Scientific Atlanta | 0Scia201 | Prisma G10 | 2.0.0 | 2.0.0 | 1Jnpr211 | D1.0 | |
| 21 | D1.1 | CM | Scientific Atlanta | Scie211 | WebSTAR DPX100 | 1.1.2 r1 | 2.1 | | D1.1 | |
| 20 | D1.0 | CM | Motorola | Moto201 | SB4100 | 0.4.3.3p | Rev. 0 | | D1.0 | |
| 20 | D1.1 | CM | Tellabs | Tell201 | CVM410A | V3.20 | V1.A | | D1.1 | |
| 20 | D1.1 | CM | Scientific Atlanta | Scie202 | WebSTAR DPX100 | 1.1.1 r1 | 2.0 | | D1.1 | |
| 20 | D1.1 | CM | Ericsson | Eric201 | HM206C | CXC 112 22391/1 R1B | ROA 117 8493/1 R2A | | D1.1 | |
| 20 | D1.1 | CM | Ambit | Ambi201 | 60194E | 2.25.988 | 1.8 | | D1.1 | |
| 20 | D1.0 | CM | Toshiba | Tosh201 | PCX2500 / DAZ8821 | 1.0.2 | 9.1.0 | | D1.0 | |
| 20 | D1.0 | CM | Thomson | Thom201 | RCA DCM245 | ST13.05.00 | 26 | | D1.0 | |
| 20 | D1.0 | CM | Scientific Atlanta | Scie201 | WebSTAR DPX100 | 1.0.5 r1 | 1.0 | | D1.0 | |
| 20 | D1.1 | CM | Texas Instruments | Texa201 | TNETC405T | 4.0.9 | 9.0 | | D1.1 | |
| 20 | D1.0 | CM | Motorola | Moto202 | SB4200 | 0.4.3.3p | Rev. 1 | | D1.0 | |
| 20 | D1.1 | CM | Arris | Arri201 | A2TM01NA | 1.1.0 | 02 | | D1.1 | |
| 20 | D1.0 | CM | Hitron | Hitr201 | BRG-3520 | 1.0.1 | 3A | | D1.0 | |
| 20 | D1.0 | CM | D-Link | Dlin201 | DCM-200 | 4.4382.1 | 3.2 | | D1.0 | |
| 20 | D1.0 | CM | Cisco | Cisc201 | UBR925 | Ver 12.2 | 3.j | | D1.0 | |
| 20 | D1.0 | CM | Ambit | Ambi202 | 60237EUW | 5.1.309 | 4.2 | | D1.0 | |
| 20 | D1.0 | CM | 3Com | 3Com201 | 3CR29223 | 01.22 | 2.00 | | D1.0 | |
| 20 | D1.1 | CMTS | Cisco | 1Cisc201 | UBR7200 VXR/MC16S | 12.1(7)CX2 | rev B0 MC16S rev 1.0 | | D1.1 | |
| 20 | D1.0 | CM | Panasonic | Pana201 | TZ-CM200 | 1.7.14 | 2.1 | | D1.0 | |
| 20 | D1.0 | CMTS | Pacific Broadband | 0Pbco201 | Kodiak G10 | 2.0.0.16 | 2.0.0 (M2.0/A1.2/D2.0) | | D1.0 | |
| 20 | D1.1 | CM | Toshiba | Tosh203 | PCX3000 / DAZ8831 | 2.2.3 | 13.0.0 | | D1.1 | |
| 20 | D1.0 | CMTS | Cisco | 0Cisc201 | UBR10012 | 12.2(2)XF1 | rev 3.0 MC28 Rev A0 | | D1.0 | |
| 20 | D1.1 | CM | Toshiba | Tosh202 | PCX2500 / DAZ8821 | 2.0.3 | 9.1.0 | | D1.1 | |
| 20 | D1.0 | CM | Toshiba | Tosh204 | PCX2200 / DAZ8817 | 1.7.014 | 7.1 | | D1.0 | |
| 19 | D1.0 | CM | Askey | Aske192 | CME063 | 1.0.4 Release 2 | 4.0 | Scie191 | D1.0 | |
| 19 | D1.0 | CM | Samsung | Same191 | SCM-120U | 1.1.1 | 12.20 | | D1.0 | |
| 19 | D1.0 | CM | Scientific Atlanta | Scie191 | WebSTAR DPX110 | 1.0.4 Release 2 | 4.0 | | D1.0 | |
| 19 | D1.0 | CM | Scientific Atlanta | Scie192 | WebSTAR DPX110 | 1.0.4 Release 2 | 3.0 | | D1.0 | |
| 19 | D1.0 | CM | Terayon | Tera191 | ECM610 | 3.47 | 1.2 | | D1.0 | |
| 19 | D1.0 | CM | Thomson | Thom191 | DCM245 / DCM245R | ST12.07.01 | 26 | | D1.0 | |
| 19 | D1.0 | CM | Correlant | Corr191 | EC280T | 1.7.11 | 7.11 | | D1.0 | |
| 19 | D1.0 | CM | Askey | Aske191 | CMH033 | 1.0.4 Release 2 | 3.0 | Scie192 | D1.0 | |
| 19 | D1.0 | CM | Accton | Actn191 | SMC8002CM | 4.5096 | 9414.18.0 | | D1.0 | |
| 19 | D1.0 | CM | Hauppauge Computer | Haup191 | BRG-3510 | 1.0.9M1.2 | A0 | Hitr181 | D1.0 | |
| 19 | D1.0 | CM | LG Innotek | Lgin192 | LCM5000 | 1.0.9M1.2 | A0 | Hitr181 | D1.0 | |
| 19 | D1.0 | CM | Terayon | Tera192 | ECM615 | 3.52 | 1.2 | | D1.0 | |
| 19 | D1.0 | CM | CastleNet | Cast191 | CXC110 | 0.5096.360 | 04 | | D1.0 | |
| 19 | D1.0 | CM | Ericsson | Eric191 | HM200c | CXC 112 2096/1 R5B | ROA 117 8439/1 R2A | | D1.0 | |
| 19 | D1.0 | CM | Ericsson | Eric192 | HM204c | CXC 112 2096/1 R5B | ROA 117 8439/1 R2A | | D1.0 | |
| 19 | D1.0 | CM | Ericsson | Eric193 | HM200c | R3G | R2B | | D1.0 | |
| 19 | D1.0 | CM | High Speed Surfing | High191 | SM200 | 0.5096.360 | 02 | | D1.0 | |
| 19 | D1.0 | CM | LG Innotek | Lgin191 | LCM100 | 4.5096 | 03 | | D1.0 | |
| 19 | D1.0 | CM | Motorola | Moto191 | SB4000 | 4.2.12p | Rev. 1 | | D1.0 | |
| 19 | D1.0 | CM | Motorola | Moto192 | SB4100 | 4.0.12P | Rev. 0 | | D1.0 | |
| 19 | D1.0 | CM | Tri-Gem Computer | Trig191 | Dream Port-1200 | 1.0.9M1.2 | A0 | Hitr181 | D1.0 | |
| 19 | D1.0 | CM | Motorola | Moto193 | SB4101 | 4.0.12P | Rev. 4 | | D1.0 | |
| 19 | D1.0 | CM | SMC | Smcn191 | SMC 8002 CM | 2.8.3 | 1.6 | Ambi181 | D1.0 | |
| 19 | D1.0 | CM | Panasonic | Pana191 | TZ-CM200 | 1.7.11 | 2.1 | Correlant EC280T | D1.0 | |
| 19 | D1.0 | CM | AsusTek | Asus191 | ACM6050EB | 1.60 | 1.30 | | D1.0 | |
| 19 | D1.0 | CM | Ambit | Ambi191 | 60194E | 2.22.2 | 1.8 | | D1.0 | |
| 19 | D1.1 | CMTS | Cadant | 1Cada191 | C4-CMTS-2100 | v00.80.17 | 1.0 | | D1.1 | |
| 19 | D1.1 | CMTS | Arris | 1Arri191 | Cornerstone CMTS 1500 | 4.2.0 | 01 | | D1.1 | |
| 19 | D1.0 | CM | Toshiba | Tosh192 | PCX1500/DAZ8816 | 1.7.011 | 7.1 | | D1.0 | |
| 19 | D1.0 | CM | Toshiba | Tosh194 | PCX1200/DAZ8815 | 1.7.011 | 7.0 | | D1.0 | |
| 19 | D1.0 | CM | Turbocomm | Turb191 | EC200T | 1.7.11 | 7.0 | Correlant EC280T | D1.0 | |
| 19 | D1.0 | CM | Zoom | Zoom191 | Zoom Cable Modem 5041 | 4.100 | 140 | | D1.0 | |
| 19 | D1.0 | CMTS | Motorola | 0Moto191 | DCM-2100 | Release 11x | 484447-001 Rev A | | D1.0 | |
| 19 | D1.1 | CM | Toshiba | Tosh193 | PCX2500/DAZ8821 | 2.0.1 | 9.0.0 | | D1.1 | |
| 19 | D1.1 | CM | Texas Instruments | Texa191 | TNETC405 | 2.0.1 | 2.0.0 | | D1.1 | |

| CW | Version | Type | Manufacturer | CL ID | Model # | SW Version | HW Version | OEM Vendor ID | Spec Combo - Certified As | Verified For Interoperability |
|----|---------|------|--------------------|----------|-----------------------|---------------------------|--|---------------|---------------------------|-------------------------------|
| 18 | D1.0 | CM | Ericsson | Eric182 | HM204c | CXC112 2096/1 R5A | ROA117 8439/1 R2A | | D1.0 | |
| 18 | D1.0 | CM | Linksys | Link181 | BEUCM11 | 0.4381.108 | 04 | Cast172 | D1.0 | |
| 18 | D1.0 | CM | Ericsson | Eric181 | HM200c | CXC112 2096/1 R5A | ROA117 8439/1 R2A | | D1.0 | |
| 18 | D1.0 | CM | D-Link | Dlin181 | DCM-200 | 4.4382 | 3.2 | Powe171 | D1.0 | |
| 18 | D1.0 | CM | Net & Sys | Nets181 | MNG2000 | 2.1.0 | 4.0 | | D1.0 | |
| 18 | D1.0 | CM | Ericsson | Eric183 | HM200c | R3D | R2B | | D1.0 | |
| 18 | D1.0 | CM | Samsung | Same181 | SCM-120U | 1.0.0 | 20 | | D1.0 | |
| 18 | D1.0 | CM | Zoom | Zoom181 | 5001 | 1.86 | 0295-014 (MIB:295014) | | D1.0 | |
| 18 | D1.0 | CM | US Robotics | Usro181 | USR6000 | 2.13.2 | 1.6 | Ambit | D1.0 | |
| 18 | D1.0 | CM | Thomson | Thom181 | DCM245/245R | ST12.07 | 26 | | D1.0 | |
| 18 | D1.0 | CM | Toshiba | Tosh181 | PCX 2000/DAZ8820 | 1.1R.006 | 3.3.2 | | D1.0 | |
| 18 | D1.0 | CM | 3Com | 3Com183 | 3CR29250 | 2.16.1 | 1.6 | Ambit | D1.0 | |
| 18 | D1.0 | CM | High Speed Surfing | High181 | SM100 | 0.4381.108 | 04 | Cast172 | D1.0 | |
| 18 | D1.0 | CM | Ambit | Ambi181 | 60194E | 2.8.3 | 1.6 | | D1.0 | |
| 18 | D1.0 | CM | Castlenet | Cast181 | CXC110-Dual Link | 0.4590.230 | 04 | | D1.0 | |
| 18 | D1.0 | CM | 3Com | 3Com181 | 3CR29250 | 2.10.5 | 1.6 | Ambit | D1.0 | |
| 18 | D1.0 | CMTS | Pacific Broadband | 0Pbco181 | KODIAK F10 | 1.1.0.17 | M1.1 / A1.7 / D1.1 | | D1.0 | |
| 18 | D1.0 | CM | Infinite | Infii181 | ICM1150T | VCMxm v1.8 | ICM1150T Rev D | | D1.0 | |
| 18 | D1.0 | CM | Hitron | Hitr182 | BWG-3511 | 1.0.9W1.3 | A0 | | D1.0 | |
| 18 | D1.0 | CM | Hitron | Hitr181 | BRG-3510 | 1.0.9M1.2 | A0 | | D1.0 | |
| 18 | D1.0 | CM | Toshiba | Tosh182 | PCX 2000/DAZ8820 | 1.1R.005 | 3.2.1 | | D1.0 | |
| 17 | D1.0 | CM | Samsung | Sama171 | SCM-130U | V2.1.0 | 13/10 | | D1.0 | |
| 17 | D1.0 | CM | Samsung | Sams171 | SCM-120R | 4.4381 | 12.00 | | D1.0 | |
| 17 | D1.0 | CM | Askey | Aske171 | CME063 | 1.0.3R4 | 3.0 | | D1.0 | |
| 17 | D1.0 | CM | Cisco | Cisc171 | CVA 122 | cva120-k1v4y5-mz.TLN | 3.t | | D1.0 | |
| 17 | D1.0 | CM | High Speed Surfing | High171 | SM110 | 0.4381.108 | 04 | | D1.0 | |
| 17 | D1.0 | CM | Terayon | Tera171 | ECM210 | 1.7.8 | 6.62 | Correlant | D1.0 | |
| 17 | D1.0 | CM | Texas Instruments | Texa171 | TNETC400G | .217 | 3.2 | | D1.0 | |
| 17 | D1.0 | CM | Scientific Atlanta | Scie171 | Webstar DPX-110 | 1.0.3R4 | 3.0 | Aske171 | D1.0 | |
| 17 | D1.0 | CM | Ericsson | Eric171 | HM200c R1A (ZAT 510 | R3D | R1A | | D1.0 | |
| 17 | D1.0 | CM | Nortel Networks | Nort171 | 102/14) | 1.0.3R4 | 3.0 | Aske171 | D1.0 | |
| 17 | D1.0 | CM | Motorola | Moto174 | CM115U | 4.0.9p | Rev 3 | | D1.0 | |
| 17 | D1.0 | CM | Motorola | Moto173 | SB4100 Rev 3 | 4.0.9p | Rev 1 | | D1.0 | |
| 17 | D1.0 | CM | Motorola | Moto173 | SB4100 Rev 1 | 4.0.9p | Rev 1 | | D1.0 | |
| 17 | D1.0 | CM | Matsushita | Mats171 | TZ-CM100 | 1.1 | 1.1 | | D1.0 | |
| 17 | D1.0 | CM | Motorola | Moto171 | Moto171 | 3.2.12p | Rev 1 | | D1.0 | |
| 17 | D1.0 | CM | Dakos | Dako171 | CableXpert CMZ1100 | 4.0.43.81 | 1.0 | | D1.0 | |
| 17 | D1.0 | CM | Castlenet | Cast172 | CXC110-CTI | 0.4381.108 | 04 | | D1.0 | |
| 17 | D1.0 | CM | ElsaAG | Elsa171 | Microlink Cable | 1.0.8 | A3 | GVC | D1.0 | |
| 17 | D1.0 | CM | Motorola | Moto172 | SB4100 Rev 0 | 4.0.9p | Rev 0 | | D1.0 | |
| 17 | D1.0 | CM | Global Telemann | Gtsc171 | MediaLynx CM-2000 | K | MediaLynx CM-2000 | | D1.0 | |
| 17 | D1.0 | CM | Ericsson | Eric172 | HM204c R1A (ZAT 510 | R4A | R1A | | D1.0 | |
| 17 | D1.0 | CM | Castlenet | Cast171 | 112/14) | 0.4381.108 | 04 | | D1.0 | |
| 17 | D1.0 | CM | Powercom | Powe171 | CXC110-iCabler | 4.4382 | V3.2 | | D1.0 | |
| 17 | D1.0 | CMTS | Arris | 0Arri171 | Cornerstone CMTS-1500 | 4.0.0 | 00 | | D1.0 | |
| 17 | D1.0 | CMTS | Tellabs | 0Tell171 | Cablespace 2700 | 6.1.2.C.1 | Backplane: 300-005-06-0A CMTS module: -2 | | D1.0 | |
| 17 | D1.0 | CMTS | Terayon | 0Tera171 | BE 2000/BE-CMTS41 | 6.1.2.C.1 | 0A CMTS module: 02 | | D1.0 | |
| 17 | D1.0 | CMTS | Cisco | 0Cisc172 | UBR 7100 | ubr7100-k1p-mz.121-4.4.EC | Line card rev 3 | | D1.0 | |
| 17 | D1.0 | CMTS | RiverStone | 0Rstn171 | RS 8000 | 6.1.2.C.1 | upconv:rev 7 | | D1.0 | |
| 17 | D1.0 | CM | 3Com | 3Com173 | 3CR29241 | 01.03 | Backplane: 300-001-05-0A CMTS module 02 | | D1.0 | |
| 17 | D1.0 | CM | 3Com | 3Com172 | 3CR29223 | 01.15 | 2.0 | | D1.0 | |
| 17 | D1.0 | CM | Accton | Acct171 | SMC 8001 | 2.1.0 | 2/1 | | D1.0 | |
| 16 | D1.0 | CM | Zoom | Zoom161 | 5031 | 2.0.42.70 | 029301 | | D1.0 | |
| 16 | D1.0 | CMTS | RiverDelta | 0Rdel161 | BSR64000 | 00.01.00.BA | CHS-0001-02 | | D1.0 | |
| 16 | D1.0 | CM | Toshiba | Tosh161 | DAZ8813 | 1.7.007 | 6.62 | | D1.0 | |
| 16 | D1.0 | CM | Nortel Networks | Nort161 | CM220 | v2.4 patch 1 | V1.4 | Ambit | D1.0 | |
| 16 | D1.0 | CMTS | Cisco | 0Cisc161 | UBR7200/MC28C | 12.1(3a)EC | A0 | | D1.0 | |
| 16 | D1.0 | CM | ElsaAG | Elsa161 | 204 | 1.30 | G | | D1.0 | |
| 16 | D1.0 | CM | Ambit | Ambi161 | 60218P | v2.2 patch:9 | v3.1 | | D1.0 | |
| 16 | D1.0 | CM | D-Link | Dlin161 | DCM100 | 4.4270 | 3.2 | | D1.0 | |

| CW | Version | Type | Manufacturer | CL ID | Model # | SW Version | HW Version | OEM Vendor ID | Spec Combo - Certified As | Verified For Interoperability |
|----|---------|------|----------------------|----------|------------------|-----------------------|-----------------------|----------------------|---------------------------|-------------------------------|
| 15 | D1.0 | CM | Askey | Aske151 | RT080 | 1.10.0 | V8.0 | | | |
| 15 | D1.0 | CMTS | RiverDelta | 0Rdel152 | BSR 1000 | 2.1.9 | BSR 1000 | | | |
| 15 | D1.0 | CM | Toshiba | Tosh152 | PCX1100/DAZ8811 | 1.7.006 | 6.12 | | | |
| 15 | D1.0 | CM | Maspro | Masp151 | 77TCM2 | V1.0 | V1.C | | | |
| 15 | D1.0 | CM | Toshiba | Tosh153 | PCX1100U/DAZ8813 | 1.7.006 | 6.62 | | | |
| 15 | D1.0 | CM | Lucent (Delta Kabel) | Luce151 | Demos 38-033 | V2.91.0 | v8.0 | Aske131 | | |
| | | | | | | | Chassis: rev B; CMTS: | | | |
| 15 | D1.0 | CMTS | RiverStone | 0Rstn151 | RS 8000 | 6.1.0.1 | Rev 02 | | | |
| 15 | D1.0 | CM | Cisco | Cisc151 | UBR905 | ubr925-k1k2o3sv4y5-mz | A0 | | | |
| 15 | D1.0 | CM | Ambit | Ambi151 | 60194E | 2.2.7 | 1.4 | | | |
| | | | | | | | Chassis: revB; CMTS: | | | |
| 15 | D1.0 | CMTS | Terayon | 0Tera151 | CMTS41A | 6.1 | Rev. 2 | | | |
| 15 | D1.0 | CM | Net & Sys | Nets151 | MNG-1000 | 2.20d | 1.03 | | | |
| 15 | D1.0 | CM | 3Com | 3Com151 | 3CR29223 | v 1.10 | v 2.00 | | | |
| 15 | D1.0 | CM | Ol'e | Olee151 | C1001 | 1.0.3657 | 01 | | | |
| 15 | D1.0 | CMTS | Cisco | 0Cisc151 | UBR 7200 VXR | 12.1(2)EC1 | A0 | | | |
| 15 | D1.0 | CM | Arris | Arri151 | CM200R | ST1.08 | 25 | Thomson | | |
| 15 | D1.0 | CM | Terayon | Tera151 | ECM110 | 1.7.6 | 6.12 | | | |
| | | | | | | | DCM 2000 475390-001- | | | |
| 15 | D1.0 | CMTS | Motorola | 0Moto151 | | Rev 1.0 | 475995-001-00 Rev 01 | | | |
| 15 | D1.0 | CM | Thomson | Thom151 | DCM235/235R | ST 1.0A | 25 | | | |
| 15 | D1.0 | CM | Terayon | Tera152 | ECM210 | 1.7.6 | 6.62 | | | |
| 15 | D1.0 | CM | Motorola | Moto152 | SB3100 Rev C | Rev v3.2.9 | Rev C | | | |
| 15 | D1.0 | CM | Com21 | Comto151 | DP1110 | 2.1.0.100 | 6 | | | |
| 15 | D1.0 | CM | Saejin | Saej151 | SC-5100E | V1.13 | V1.2 | | | |
| 15 | D1.0 | CM | CIS | Ciss151 | WS-CM30EDTE | v2.14 | v1.0 | | | |
| 15 | D1.0 | CM | Future Networks | Futu152 | FN110C | V2.15 | V1.C | | | |
| 15 | D1.0 | CM | Terayon | Tera153 | TCM310 | 0036-58 | D | | | |
| 15 | D1.0 | CM | ElsaAG | Elsa151 | 204 | 1.18 | E | | | |
| 14 | D1.0 | CM | D-Link | Dlin141 | DCM100 | 0.44.32.52 | Rev 2.3 | PowerCom | | |
| 14 | D1.0 | CM | DX Antenna | Dxan141 | DAZ8811 | 1.7.003 | 6.11 | Tosh131 | | |
| 14 | D1.0 | CM | GVC | Gvcc141 | CMI-004/CON | Rev 1.44.32.52 | Rev 31 | | | |
| 14 | D1.0 | CMTS | Arris | 0Arri142 | CMTS-1000 | 3.2.1 | Rev 08 | | | |
| | | | | | | | | TurboNet | | |
| 14 | D1.0 | CM | Com21 | Comto141 | DP121 | 1.6.19 | 6.6 | Communications | | |
| 14 | D1.0 | CMTS | Cisco | 0Cisc141 | UBR 7200 VXR | 12.0(11)SC | A0 | | | |
| | | | | | | | | Engine, MVME2306-900 | | |
| 14 | D1.0 | CMTS | Motorola | 0Moto142 | MLLN 4004D | 5.2 | MRX, 74267G01, Rev C | | | |
| 14 | D1.0 | CM | Ericsson | Eric142 | HM200c | Rev R1E | Rev R2B | | | |
| 14 | D1.0 | CM | Ericsson | Eric141 | HM200c | Rev R1D | Rev R2B | | | |
| 14 | D1.0 | CM | AsusTek | Asus141 | ACM6000EB | 2.3 | 1.3 | | | |
| 14 | D1.0 | CM | Powercom | Power141 | PCR-2600 | 0.44.32.51 | Rev 2.3 | | | |
| 14 | D1.0 | CM | Ambit | Ambi141 | 60098E | 2.0.13 | 1.3 | | | |
| 14 | D1.0 | CM | Terayon | Tera141 | ECM210 | Rev 1.6.19 | Rev 6.6 | TurboNet | | |
| 14 | D1.0 | CM | Ambit | Ambi142 | 60098U | 2.0.5 | 2.0 | | | |
| 14 | D1.0 | CM | Arris | Arri141 | CM200U | ST 5.14 | V25 | RCA | | |
| 14 | D1.0 | CM | Thomson | Thom141 | DCM 225 | Ver 5.14 | Ver 25 | | | |
| 14 | D1.0 | CM | Samsung | Sams141 | SCM-110R Ether | Rev 2.0.2 | Rev 11.10 | | | |
| 14 | D1.0 | CM | Motorola | Moto143 | SB3100 Rev C | Rev 3.2.6 | Rev C | | | |
| 14 | D1.0 | CM | Zoom | Zoom142 | 5011 | 0.44.32.52 | 0293-01C | | | |
| 14 | D1.0 | CM | Motorola | Moto141 | SB3100 Rev D | Rev v3.2.6 | Rev D | | | |
| 14 | D1.0 | CM | Zoom | Zoom141 | 5001 | 1.44.32.52 | 0295-01 | | | |
| 13 | D1.0 | CM | 3Com | 3Com133 | 3CR29220 | 1.0.4 | 2.00 | | | |
| | | | | | | | | ubr920-k1y5- | | |
| 13 | D1.0 | CM | Cisco | Cisc131 | UBR924 | mz.1208TLN | A0 | | | |
| 13 | D1.0 | CM | Toshiba | Tosh131 | DAZ8811 | 1.7.003 | 6.11 | | | |
| 13 | D1.0 | CM | Alcatel | Alca131 | UM141 | 1.7.3 | 6.10 | | | |
| 13 | D1.0 | CM | 3Com | 3Com132 | 3CR29220 | 0.1.03 | 2.00 | | | |
| 13 | D1.0 | CM | Joohong | Jooh131 | Superlink 2000 | 1.7.3 | 6.1 | | | |
| 13 | D1.0 | CM | Toshiba | Tosh132 | DAZ8813 | 1.6.018 | 6.6 | | | |
| 13 | D1.0 | CM | Askey | Aske131 | CME033 | V2.91.0 | V8.0 | | | |
| 13 | D1.0 | CM | Sohoware | Soho131 | NSC200 | 1.7.3 | 6.10 | | | |
| 13 | D1.0 | CM | NetGear | Netg131 | CM201 | 2.80 | 6.0 | Aske121 | | |
| 13 | D1.0 | CM | Nortel Networks | Nort131 | CM115 | V2.91.0 | V8.0 | | | |
| 13 | D1.0 | CM | NetGame | Neta131 | Phazer | 2.80 | 6.0 | Aske121 | | |
| 13 | D1.0 | CM | GVC | Gvcc131 | CMX-SO | 3.1.0 | B | | | |

| CW | Version | Type | Manufacturer | CL ID | Model # | SW Version | HW Version | OEM Vendor ID | Spec Combo - Certified As | Verified For Interoperability |
|----|---------|------|--------------------|----------|------------------|-----------------|---|---------------|---------------------------|-------------------------------|
| 13 | D1.0 | CM | 3Com | 3Com131 | 3CR29210 | 3.1.0 | B.2 | | D1.0 | |
| 13 | D1.0 | CMTS | 3Com | 03Com135 | 8R-003678-10 | 4.4.18 | Rev B | | D1.0 | |
| 13 | D1.0 | CM | Best Data | Best131 | CMX110 | 1.7.3 | 6.10 | | D1.0 | |
| 13 | D1.0 | CM | ZyXel | Zyxe131 | 941 | 2.4 | Zygate v1.58 | | D1.0 | |
| 13 | D1.0 | CM | Motorola | Moto133 | SB3100 Rev C | v3.2.1 | Rev C | | D1.0 | |
| 13 | D1.0 | CMTS | 3Com | 03Com134 | 80-000971-01 | 3.61.48-1 | Rev 1.0 | | D1.0 | |
| 13 | D1.0 | CMTS | BAS | 0Bass131 | Cuda | 0.1.58 | D | | D1.0 | |
| 13 | D1.0 | CM | Future Networks | Futu131 | 100L | V2.13 | V2.2 | | D1.0 | |
| 13 | D1.0 | CM | Future Networks | Futu132 | 110L | V2.13 | V1.0 | | D1.0 | |
| 12 | D1.0 | CM | 3Com | 3Com121 | 2940 | 2.03 | L3 | | D1.0 | |
| 12 | D1.0 | CM | Arris | Arri122 | CM200 | ST 4.06 | V24 | | D1.0 | |
| 12 | D1.0 | CM | Thomson | Thom123 | DCM 225 | ST5.05 | V25 | | D1.0 | |
| 12 | D1.0 | CM | Arris | Arri121 | CM200U | ST 5.05 | V25 | | D1.0 | |
| 12 | D1.0 | CM | Askey | Aske121 | CME030 | v2.80 | v6.0 | | D1.0 | |
| 12 | D1.0 | CM | High Speed Surfing | High121 | SM100 | 1.6.16 | 6.1 | | D1.0 | |
| 12 | D1.0 | CM | Thomson | Thom122 | DCM 215 | ST4.0b | V24 | | D1.0 | |
| 12 | D1.0 | CM | Thomson | Thom121 | DCM 215 | ST5.05 | V24 | | D1.0 | |
| 12 | D1.0 | CM | Turbocomm | Turb121 | CM110 | 1.6.16 | 6.1 | | D1.0 | |
| 12 | D1.0 | CM | Terayon | Tera121 | ECM100 | 1.6.16 | 6.1 | | D1.0 | |
| 12 | D1.0 | CM | Terayon | Tera122 | ECM110 | 1.6.16 | 5.4 | | D1.0 | |
| 12 | D1.0 | CM | Motorola | Moto122 | MMLN3150A | 2.0.0t51 | 74362G01 | | D1.0 | |
| 12 | D1.0 | CM | Motorola | Moto121 | MLN6200A | 1.0CL08 | 75087G01 | | D1.0 | |
| 12 | D1.0 | CM | Toshiba | Tosh122 | DAZ8811 | 1.7.002 | 6.1 | | D1.0 | |
| 12 | D1.0 | CM | Dassault | Dass121 | WD020 | v2.80 | v6.0 | | D1.0 | |
| 12 | D1.0 | CM | Com21 | Cmto123 | DP111 | 1.6.16 | 6.1 | | D1.0 | |
| 12 | D1.0 | CM | Toshiba | Tosh121 | DAZ8811 | 1.6.016 | 6.1 | | D1.0 | |
| 11 | D1.0 | CM | Com21 | Cmto114 | DP101 | 1.6.14 | 5.4 | | D1.0 | |
| 11 | D1.0 | CM | Com21 | Cmto112 | CP3001 | 1.0.5.100 | 6500106 rev55 | | D1.0 | |
| 11 | D1.0 | CM | Thomson | Thom111 | DCM 205 | ST 1.10 | ver 16 | | D1.0 | |
| 11 | D1.0 | CMTS | Cisco | 0Cisc111 | UBR7200 | 11.3(11a)NA1 | A0 | | D1.0 | |
| 11 | D1.0 | CM | Com21 | Cmto113 | CP3001 | 1.1.0.100 | 6500106 rev55 | | D1.0 | |
| 11 | D1.0 | CM | DX Antenna | Dxan111 | DAZ8801D | 1.6.003 | 5.21 | Tosh092 | D1.0 | |
| 11 | D1.0 | CM | General Instrument | Gene112 | SB3100B | V3.0.7 | -001RevB | | D1.0 | |
| 11 | D1.0 | CM | Best Data | Best111 | CMX100 | 1.6.14 | 5.4 | | D1.0 | |
| 11 | D1.0 | CM | General Instrument | Gene111 | SB3100A | V3.0.7 | -002RevA | | D1.0 | |
| 11 | D1.0 | CM | Com21 | Cmto111 | CP3001 | 1.0.1.100 | 6500087 rev54 | | D1.0 | |
| 10 | D1.0 | CM | Thomson | Thom101 | DCM 105 | ST 20.5.3 | HW Ver 12 | | D1.0 | |
| 10 | D1.0 | CM | Terayon | Tera101 | ECM100 | 1.6.9 | 5.4 | | D1.0 | |
| 9 | D1.0 | CMTS | Arris | 0Arri091 | DE3801E02 | 2.0.0 | 03 | | D1.0 | |
| 9 | D1.0 | CM | Toshiba | Tosh092 | PCX1000/DAZ8801F | Ver 1.6.003 | Ver 5.21 | | D1.0 | |
| 9 | D1.0 | CM | Philips | Phil091 | PD10D | 1.76 | 1.11 | | D1.0 | |
| 9 | D1.0 | CM | Sony | Sony091 | CMR-1000 | 1.1 (0.76.1) | 1.1 | | D1.0 | |
| 9 | D1.0 | CM | Askey | Aske091 | CME010 | 1.76 | 1.11 | | D1.0 | |
| | | | | | | | MAC, 74029G01, Rev A Engine, MVME2306- 900MTX-HI, 74612G01, Rev16=RevA MTX-LO, 74608G01, Rev 02 | | | |
| 9 | D1.0 | CM | Motorola | Moto091 | MMLN4004D | 5.0t10p13b | MRX, 74267G01, Rev C | | D1.0 | |
| | | | | | | | 11.3(9)NA ubr900-k1y4- mz.cablelabs.13may99 | | | |
| 9 | D1.0 | CM | Cisco | Cisc091 | UBR904 | SCM-100R | 1.1.76 | A0 | D1.0 | |
| 9 | D1.0 | CM | Samsung | Sams091 | 3CR292-DE56 | 12.30 | 1.2 | | D1.0 | |
| 8 | D1.0 | CM | 3Com | 3Com081 | DE3804E25 | 1.100.3 | A01-3 | | D1.0 | |
| 8 | D1.0 | CMTS | Arris | 0Arri081 | SB2100 | V1.1.1 | 02 | | D1.0 | |
| 8 | D1.0 | CM | General Instrument | Gene081 | DAZ8801E | V1.1.1 | X3/002 | | D1.0 | |
| 7 | D1.0 | CM | Toshiba | Tosh071 | UBR7200 | 1.51k | 5.2 | | D1.0 | |
| 7 | D1.0 | CMTS | Cisco | 0Cisc071 | DCM 105 | 11.3(7)NA | A0 | | D1.0 | |
| 7 | D1.0 | CM | Thomson | Thom071 | ST8.4 | Pilot 3 c Rev's | | | D1.0, CH1.0 | |